


Dual-Core Intel® Xeon® Processor 7100 Series

Specification Update

August 2006

Notice: The Dual-Core Intel® Xeon® Processor 7100 Series may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.



INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL® PRODUCTS. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER, AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY RELATING TO SALE AND/OR USE OF INTEL PRODUCTS, INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT, OR OTHER INTELLECTUAL PROPERTY RIGHT.

Intel products are not intended for use in medical, life saving, life sustaining, critical control or safety systems, or in nuclear facility applications.

Intel may make changes to specifications and product descriptions at any time, without notice.

Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined." Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them.

The Dual-Core Intel® Xeon® Processor 7100 Series Processor 7110, 7120, 7130 and 7140 may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Contact your local Intel sales office or your distributor to obtain the latest specifications and before placing your product order.

¹Hyper-Threading Technology requires a computer system with an Intel® processor supporting HT Technology and a Hyper-Threading Technology enabled chipset, BIOS and operating system. Performance will vary depending on the specific hardware and software you use. See <<http://www.intel.com/products/ht/hyperthreading_more.htm>> for more information including details on which processors support HT Technology.

^Φ Intel® Extended Memory 64 Technology (Intel® EM64T) requires a computer system with a processor, chipset, BIOS, operating system, device drivers and applications enabled for Intel EM64T. Processor will not operate (including 32-bit operation) without an Intel EM64T-enabled BIOS. Performance will vary depending on your hardware and software configurations. See <http://www.intel.com/technology/64bitextensions/> for more information including details on which processors support EM64T or consult with your system vendor for more information.

[±]Intel® Virtualization Technology requires a computer system with an enabled Intel® processor, BIOS, virtual machine monitor (VMM) and for some uses, certain platform software enabled for it. Functionality, performance or other benefit will vary depending on hardware and software configurations. Intel Virtualization Technology-enabled BIOS and VMM applications are currently in development.

^Δ Intel processor numbers are not a measure of performance. Processor numbers differentiate features within each processor family, not across different processor families. Over time processor numbers will increment based on changes in clock, speed, cache, FSB, or other features, and increments are not intended to represent proportional or quantitative increases in any particular feature. Current roadmap processor number progression is not necessarily representative of future roadmaps. See www.intel.com/products/processor_number for details.

Enhanced HALT State (C1E) and Enhanced Intel SpeedStep® Technology (EIST) for specified units of this processor available Q4/06. See the Processor Spec Finder at <http://processorfinder.intel.com> or contact your Intel representative for more information.

Celeron®, Celeron® D, Celeron® M, Intel® Core™, Intel® Core™ Duo, Intel® Core™ Solo, Intel® NetBurst®, Intel® Xeon®, Mobile Intel®, Pentium® III Processor-M, Mobile Intel® Pentium® 4 Processor-M, Pentium® II, Pentium® II Xeon®, Pentium® III, Pentium® III Xeon®, Pentium® 4, Pentium® D, Pentium® M, Pentium® Pro and the Intel® logo are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Copies of documents which have an ordering number and are referenced in this document, or other Intel literature may be obtained by calling 1-800-548-4725 or by visiting Intel's website at <http://developer.intel.com/design/litcentr>.

Copyright © 2006, Intel Corporation. All rights reserved.

*Other names and brands may be claimed as the property of others.



Contents

Revision History	4
Preface	5
Package Markings.....	7
Identification Information	8
Summary Tables of Changes	10
Errata	14
Specification Changes.....	24
Specification Clarifications	25
Documentation Changes	26



Revision History

Version	Description	Date
001	Initial release of the Dual-Core Intel Xeon® Processor 7100 Series Specification Update	August 2006



Preface

This document is an update to the specifications contained in the Affected Documents and Related Documents tables below. This document is a compilation of device and documentation errata, specification clarifications and changes. It is intended for hardware system manufacturers and software developers of applications, operating systems, or tools.

Information types defined in Nomenclature are consolidated into the specification update and are no longer published in other documents.

This document may also contain information that was not previously published.

Affected Documents

1. *Dual-Core Intel® Xeon® Processor 7100 Series Datasheet*

Related Documents

1. *IA-32 Intel® Architecture Software Developer's Manual*, Volume 1: Basic Architecture (Document Number 253665)
Link: <ftp://download.intel.com/design/Pentium4/manuals/253665.htm>
2. *IA-32 Intel® Architecture Software Developer's Manual*, Volume 2A: Instruction Set Reference, A-M (Document Number 253666)
Link: <ftp://download.intel.com/design/Pentium4/manuals/253666.htm>
3. *IA-32 Intel® Architecture Software Developer's Manual*, Volume 2B: Instruction Set Reference, N-Z (Document Number 253667)
Link: <ftp://download.intel.com/design/Pentium4/manuals/253667.htm>
4. *IA-32 Intel® Architecture Software Developer's Manual*, Volume 3A: System Programming Guide (Document Number 253668)
Link: <ftp://download.intel.com/design/Pentium4/manuals/253668.htm>
5. *IA-32 Intel® Architecture Software Developer's Manual*, Volume 3B: System Programming Guide (Document Number 253668)
Link: <ftp://download.intel.com/design/Pentium4/manuals/253669.htm>

Nomenclature

Errata are design defects or errors. These may cause the processor's behavior to deviate from published specifications. Hardware and software designed to be used with any given stepping must assume that all errata documented for that stepping are present on all devices.

S-Spec Number is a five-digit code used to identify products. Products are differentiated by their unique characteristics, e.g., core speed, L3 cache size, package type, etc. as described in the processor identification information table. Read all notes associated with each S-Spec number.

Specification Changes are modifications to the current published specifications. These changes will be incorporated in any new release of the specification.



Specification Clarifications describe a specification in greater detail or further highlight a specification's impact to a complex design situation. These clarifications will be incorporated in any new release of the specification.

QDF Number is a several digit code used to distinguish between engineering samples. These samples are used for qualification and early design validation. The functionality of these parts can range from mechanical only to fully functional. This document has a processor identification information table that lists these QDF numbers and the corresponding product sample details.

Documentation Changes include typos, errors, or omissions from the current published specifications. These will be incorporated in any new release of the specification.

Note: Errata remain in the specification update throughout the product's lifecycle, or until a particular stepping is no longer commercially available. Under these circumstances, errata removed from the specification update are archived and available upon request. Specification changes, specification clarifications and documentation changes are removed from the specification update when the appropriate changes are made to the appropriate product specification or user documentation (datasheets, manuals, etc.).

Package Markings

Dual-Core Intel® Xeon® Processor 7100 Series Processor 7110, 7120, 7130 and 7140 Package Markings

Figure 1. Processor Top-Side Markings (Example)





Figure 2. Processor Bottom-Side Markings (Example)





Identification Information

The Dual-Core Intel® Xeon® Processor 7100 Series can be identified by the following register contents:

Family ¹	Model ²	L3 Cache Descriptor ³
1111b	0110b	0x49, 0x4A, 0x4B, 0x4C or 0x4D

Notes:

1. The Family corresponds to bits [11:8] of the EDX register after RESET, bits [11:8] of the EAX register after the CPUID instruction is executed with a 1 in the EAX register, and the generation field of the Device ID register accessible through Boundary Scan.
2. The Model corresponds to bits [7:4] of the EDX register after RESET, bits [7:4] of the EAX register after the CPUID instruction is executed with a 1 in the EAX register, and the model field of the Device ID register accessible through Boundary Scan.
3. Cache and TLB descriptor parameters are provided in the EAX, EBX, ECX and EDX registers after the CPUID instruction is executed with a 2 in the EAX register. The value returned is dependant on the L3 cache size of the processor installed, see [Table 1](#).

Cache and TLB descriptor parameters are provided in the EAX, EBX, ECX and EDX registers after the CPUID instruction is executed with a 2 in the EAX register. Please refer to the *AP-485 Intel® Processor Identification and the CPUID Instruction Application Note* and the *Cedar Mill Processor Family BIOS Writer's Guide* for further information on the CPUID instruction.



Table 1. Dual-Core Intel® Xeon® Processor 7100 Series Processor 7110, 7120, 7130 and 7140 Identification Information

QDF/ S-Spec	Core Stepping	L2 Cache Size (bytes)	L3 Cache Size (bytes)	CPUID	Core Freq (GHz)	Data Bus Freq (MHz)	Package and Revision	Model Number	Notes
SL9HD	B0	1M x 2	16M	0F68h	3.333	667	604-pin micro-PGA with 53.3 x 53.3 mm FC-PGA6 packg Rev 02	7140N	1, 3
SL9HE	B0	1M x 2	8M	0F68h	3.167	667	604-pin micro-PGA with 53.3 x 53.3 mm FC-PGA6 packg Rev 02	7130N	1, 3
SL9HF	B0	1M x 2	4M	0F68h	3.000	667	604-pin micro-PGA with 53.3 x 53.3 mm FC-PGA6 packg Rev 02	7120N	2, 4
SL9QA	B0	1M x 2	4M	0F68h	2.500	667	604-pin micro-PGA with 53.3 x 53.3 mm FC-PGA6 packg Rev 02	7110N	2, 4
SL9HA	B0	1M x 2	16M	0F68h	3.400	800	604-pin micro-PGA with 53.3 x 53.3 mm FC-PGA6 packg Rev 02	7140M	1, 3
SL9HB	B0	1M x 2	8M	0F68h	3.200	800	604-pin micro-PGA with 53.3 x 53.3 mm FC-PGA6 packg Rev 02	7130M	1, 3
SL9HC	B0	1M x 2	4M	0F68h	3.000	800	604-pin micro-PGA with 53.3 x 53.3 mm FC-PGA6 packg Rev 02	7120M	2, 4
SL9Q9	B0	1M x 2	4M	0F68h	2.600	800	604-pin micro-PGA with 53.3 x 53.3 mm FC-PGA6 packg Rev 02	7120M	2, 4

Notes:

1. These parts are enabled for Enhanced Intel SpeedStep® Technology (EIST).
2. These parts are disabled for Enhanced Intel SpeedStep® Technology (EIST).
3. These parts are enabled for TM2.
4. These parts are disabled for TM2.



Summary Tables of Changes

The following table indicates the Errata, Specification Changes, Specification Clarifications, or Documentation Changes which apply to the Dual-Core Intel Xeon Processor 7100 Series. Intel may fix some of the errata in a future stepping of the component, and account for the other outstanding issues through documentation or specification changes as noted. This table uses the following notations:

Codes Used in Summary Table

Stepping

X:	Errata exists in the stepping indicated. Specification Change or Clarification that applies to this stepping.
(No mark)	
or (Blank box):	This erratum is fixed in listed stepping or specification change does not apply to listed stepping.

Page

(Page):	Page location of item in this document.
---------	---

Status

Doc:	Document change or update will be implemented.
Plan Fix:	This erratum may be fixed in a future stepping of the product.
Fixed:	This erratum has been previously fixed.
No Fix:	There are no plans to fix this erratum.

Row

	Change bar to left of table row indicates this erratum is either new or modified from the previous version of the document.
--	---

Each Specification Update item will be prefixed with a capital letter to distinguish the product. The key below details the letters that are used in Intel's microprocessor Specification Updates:

A =	Dual-Core Intel® Xeon® processor 7000 sequence
B =	Mobile Intel® Pentium® II processor
C =	Intel® Celeron® processor
D =	Dual-Core Intel® Xeon® processor 2.80 GHz
E =	Intel® Pentium® III processor
F =	Intel® Pentium® processor Extreme Edition and Intel® Pentium® D processor
G =	Intel® Pentium® III Xeon® processor
H =	Mobile Intel® Celeron® processor at 466 MHz, 433 MHz, 400 MHz, 366 MHz, 333 MHz, 300 MHz, and 266 MHz
J =	64-bit Intel® Xeon® processor MP with 1MB L2 Cache
K =	Mobile Intel® Pentium® III processor - M
L =	Intel® Celeron® D processor



M =	Mobile Intel® Celeron® processor
N =	Intel® Pentium® 4 processor
O =	Intel® Xeon® processor MP
P =	Intel® Xeon® processor
Q =	Mobile Intel® Pentium® 4 processor supporting Hyper-Threading Technology on 90-nm process technology
R =	Intel® Pentium® 4 processor on 90 nm process
S =	64-bit Intel® Xeon® processor with 800 MHz system bus
T =	Mobile Intel® Pentium® 4 processor - M
U =	64-bit Intel® Xeon® processor MP with up to 8MB L3 Cache
V =	Mobile Intel® Celeron® processor on 0.13 micron process in micro-FCPGA package
W =	Intel® Celeron® M processor
X =	Intel® Pentium® M processor on 90 nm process with 2-MB L2 cache
Y =	Intel® Pentium® M processor
Z =	Mobile Intel® Pentium® 4 processor with 533 MHz system bus
AA =	Intel® Pentium® processor Extreme Edition and Intel® Pentium® D processor on 65nm process
AB =	Intel® Pentium® 4 processor on 65 nm process
AC =	Intel® Celeron® processor in 478 Pin Package
AD =	Intel® Celeron® D processor on 65 nm process
AE =	Intel® Core™ Duo processor and Intel® Core™ Solo processor on 65nm process
AF =	Dual-Core Intel® Xeon® processor LV
AG =	Dual-Core Intel® Xeon® Processor 5100 Series
AH =	Intel® Core™ Duo Processor
AI =	Intel® Core™2 Duo processor
AL =	Dual-Core Intel® Xeon® Processor 7100 Series

The Specification Updates for the Pentium® processor, Pentium® Pro processor, and other Intel products do not use this convention.

Errata (Sheet 1 of 2)

No.	B0	Plans	Description
AL1	X	No Fix	"Bus Locks and SMC Detection May Cause the Processor to Hang Temporarily"
AL2	X	No Fix	Invalid opcode "Memory Aliasing of Pages As Uncacheable Memory Type and Write Back (WB) May Hang the System" code 0FFFh requires a ModRM byte
AL3	X	No Fix	"Data Breakpoints on the High Half of a Floating Point Line Split May Not Be Captured"
AL4	X	No Fix	"MOV CR3 Performs Incorrect Reserved Bit Checking When in PAE Paging"
AL5	X	No Fix	"VMEntry from 64-bit Host to 32-bit Guest may Cause IERR# with Hyper-Threading Enabled"
AL6	X	No Fix	"FXRSTOR May Not Restore Non-canonical Effective Addresses on Processors with Intel® Extended Memory 64 Technology (Intel® EM64T) Enabled"
AL7	X	No Fix	"A Push of ESP That Faults May Zero the Upper 32 Bits of RSP"
AL8	X	No Fix	"Checking of Page Table Base Address May Not Match the Address Bit Width Supported by the Platform"
AL9	X	No Fix	"With TF (Trap Flag) Asserted, FP Instruction That Triggers an Unmasked FP Exception May Take Single Step Trap before Retirement of Instruction"
AL10	X	No Fix	"BTS (Branch Trace Store) and PEBS (Precise Event Based Sampling) May Update Memory outside the BTS/PEBS Buffer"
AL11	X	No Fix	"Control Register 2 (CR2) Can be Updated during a REP MOVSB/STOSB Instruction with Fast Strings Enabled"



Errata (Sheet 2 of 2)

No.	B0	Plans	Description
AL12	X	No Fix	"REP STOS/MOVS Instructions with RCX $\geq 2^{32}$ May Cause a System Hang"
AL13	X	No Fix	"A 64-Bit Value of Linear Instruction Pointer (LIP) May be Reported Incorrectly in the Branch Trace Store (BTS) Memory Record or in the Precise Event Based Sampling (PEBS) Memory Record"
AL14	X	No Fix	"Access to an Unsupported Address Range in Uniprocessor (UP) or Dual-processor (DP) Systems Supporting Intel® Virtualization Technology May Not Trigger Appropriate Actions"
AL15	X	No Fix	"Two Correctable L2 Cache Errors in Close Proximity May Cause a System Hang"
AL16	X	No Fix	"Processor May Hang with a 25% or Less STPCLK# Duty Cycle"
AL17	X	No Fix	"Machine Check Exceptions May not Update Last-Exception Record MSRs (LERs)"
AL18	X	No Fix	"Writing the Local Vector Table (LVT) when an Interrupt is Pending May Cause an Unexpected Interrupt"
AL19	X	No Fix	"L2 Cache ECC Machine Check Errors May be erroneously Reported after an Asynchronous RESET# Assertion"
AL20	X	No Fix	"VMCALL to Activate Dual-monitor Treatment of SMIs and SMM Ignores Reserved Bit settings in VM-exit Control Field"
AL21	X	No Fix	"Using 2M/4M Pages When A20M# Is Asserted May Result in Incorrect Address Translations"
AL22	X	No Fix	"Writing Shared Unaligned Data that Crosses a Cache Line without Proper Semaphores or Barriers May Expose a Memory Ordering Issue"
AL23	X	No Fix	"The IA32_MC0_STATUS and IA32_MC1_STATUS Overflow Bit is not set when Multiple Un-correctable Machine Check Errors Occur at the Same Time"
AL24	X	No Fix	"IRET under Certain Conditions May Cause an Unexpected Alignment Check Exception"
AL25	X	No Fix	"Processor May Fault When the Upper 8 Bytes of Segment Selector Is Loaded from a Far Jump through a Call Gate via the Local Descriptor Table"
AL26	X	No Fix	"The Processor May Issue Front Side Bus Transactions up to 6 Clocks after RESET# is Asserted"
AL27	X	No Fix	"Front Side Bus Machine Checks May be Reported as a Result of On-Going Transactions during Warm Reset"
AL28	X	No Fix	"NMI-blocking Information Recorded in VMCS May be Incorrect after a #GP on an IRET Instruction"
AL29	X	No Fix	"VMLAUNCH/VMRESUME May Not Fail when VMCS is Programmed to Cause VM Exit to Return to a Different Mode"
AL30	X	No Fix	"A Machine Check Exception (MCE) Occurring during an Enhanced Intel SpeedStep® Technology Ratio Change May Cause Both Processor Cores to Lock Up"
AL31	X	No Fix	"BIST Error Reported on Secondary Logical Processor of Each Core"
AL32	X	No Fix	"When Enhanced Halt State is Enabled and Thermal Monitor 2 is Disabled a System Hang may Occur"
AL33	X	No Fix	"Lock Interaction between Two Logical Processors within a Core may Cause a Stall in Code Execution"
AL34	X	No Fix	"Periodic Thermal Throttling/STPCLK Events in the Presence of High Memory Latency Accesses Could Lead to a System Hang"
AL35	X	Plan Fix	"Reduced End-Agent Low side FSB Margin may occur with High Impedance Boards Operating at Low Temperatures"
AL36	X	No Fix	"L3 Cache Errors Occurring During an INVD or WBINVD Instruction May not Generate a Machine Check Exception"
AL37	X	No Fix	"A Continuous Loop Executing Bus Lock Transactions on One Logical Processor may Prevent Another Logical Processor from Acquiring Resource"



Specification Changes

No.	SPECIFICATION CHANGES
	None for this revision of this specification update.

Specification Clarifications

No.	SPECIFICATION CLARIFICATIONS
	None for this revision of this specification update.

Documentation Changes

No.	DOCUMENTATION CHANGES
	None for this revision of this specification update.



Errata

AL1. Bus Locks and SMC Detection May Cause the Processor to Hang Temporarily

Problem: The processor may temporarily hang in an HT Technology enabled system if one logical processor executes a synchronization loop that includes one or more locks and is waiting for release by the other logical processor. If the releasing logical processor is executing instructions that are within the detection range of the self-modifying code (SMC) logic, then the processor may be locked in the synchronization loop until the arrival of an interrupt or other event.

Implication: If this erratum occurs in an HT Technology enabled system, the application may temporarily stop making forward progress. Intel has not observed this erratum with any commercially available software.

Workaround: None identified.

Status: For the steppings affected, see the *Summary Tables of Changes*.

AL2. Memory Aliasing of Pages As Uncacheable Memory Type and Write Back (WB) May Hang the System

Problem: When a page is being accessed as either Uncacheable (UC) or Write Combining (WC) and WB, under certain bus and memory timing conditions, the system may loop in a continual sequence of UC fetch, implicit writeback, and Request For Ownership (RFO) retries.

Implication: This erratum has not been observed in any commercially available operating system or application. The aliasing of memory regions, a condition necessary for this erratum to occur, is documented as being unsupported in the IA-32 Intel® Architecture Software Developer's Manual, Volume 3, section 10.12.4, Programming the PAT. However, if this erratum occurs the system may hang.

Workaround: The pages should not be mapped as either UC or WC and WB at the same time.

Status: For the stepping affected, see the *Summary Tables of Changes*.

AL3. Data Breakpoints on the High Half of a Floating Point Line Split May Not Be Captured

Problem: When a floating point load which splits a 64-byte cache line gets a floating point stack fault, and a data breakpoint register maps to the high line of the floating point load, internal boundary conditions exist that may prevent the data breakpoint from being captured.

Implication: When this erratum occurs, a data breakpoint will not be captured.

Workaround: None identified.

Status: For the steppings affected, see the *Summary Tables of Changes*.

AL4. MOV CR3 Performs Incorrect Reserved Bit Checking When in PAE Paging

Problem: The MOV CR3 instruction should perform reserved bit checking on the upper unimplemented address bits. This checking range should match the address width reported by CPUID instruction 0x8000008. This erratum applies whenever PAE is enabled.

Implication: Software that sets the upper address bits on a MOV CR3 instruction and expects a fault may fail. This erratum has not been observed with commercially available software.

Workaround: None identified.



Status: For the steppings affected, see the *Summary Tables of Changes*.

AL5. VMEntry from 64-bit Host to 32-bit Guest may Cause IERR# with Hyper-Threading Enabled

Problem: When transitioning from a 64-bit host environment to a 32-bit guest environment via a VMEntry, internal conditions in a processor with Hyper-Threading enabled may cause a speculative page-table walk to be prematurely terminated, resulting in a processor hang and the assertion of IERR#.

Implication: An IERR# may occur on VMEntry from a 64-bit to a 32-bit environment with Hyper-Threading enabled.

Workaround: It is possible for the BIOS to contain a workaround for this erratum.

Status: For the steppings affected, see the *Summary Tables of Changes*.

AL6. FXRSTOR May Not Restore Non-canonical Effective Addresses on Processors with Intel® Extended Memory 64 Technology (Intel® EM64T) Enabled

Problem: If an x87 data instruction has been executed with a non-canonical effective address, FXSAVE may store that non-canonical FP Data Pointer (FDP) value into the save image. An FXRSTOR instruction executed with 64-bit operand size may signal a General Protection Fault (#GP) if the FDP or FP Instruction Pointer (FIP) is in non-canonical form.

Implication: When this erratum occurs, Intel EM64T enabled systems may encounter an unintended #GP fault.

Workaround: Software should avoid using non-canonical effective addressing in EM64T enabled processors. BIOS can contain a workaround for this erratum removing the unintended #GP fault on FXRSTOR.

Status: For the steppings affected, see the *Summary Tables of Changes*.

AL7. A Push of ESP That Faults May Zero the Upper 32 Bits of RSP

Problem: In the event that a push ESP instruction, that faults, is executed in compatibility mode, the processor will incorrectly zero upper 32-bits of RSP.

Implication: A Push of ESP in compatibility mode will zero the upper 32-bits of RSP. Due to this erratum, this instruction fault may change the contents of RSP. This erratum has not been observed in commercially available software.

Workaround: None identified.

Status: For the steppings affected, see the *Summary Tables of Changes*.

AL8. Checking of Page Table Base Address May Not Match the Address Bit Width Supported by the Platform

Problem: If the page table base address, included in the page map level-4 table, page-directory pointer table, page-directory table or page table, exceeds the physical address range supported by the platform (e.g. 36-bit) and it is less than the implemented address range (e.g. 40-bit), the processor does not check if the address is invalid.

Implication: If software sets such invalid physical address in those tables, the processor does not generate a page fault (#PF) upon access to that virtual address, and the access results in an incorrect read or write. If BIOS provides only valid physical address ranges to the operating system, this erratum will not occur.

Workaround: BIOS must provide valid physical address ranges to the operating system.

Status: For the steppings affected, see the *Summary Tables of Changes*.

**AL9. With TF (Trap Flag) Asserted, FP Instruction That Triggers an Unmasked FP Exception May Take Single Step Trap before Retirement of Instruction**

Problem: If an FP instruction generates an unmasked exception with the EFLAGS.TF=1, it is possible for external events to occur, including a transition to a lower power state. When resuming from the lower power state, it may be possible to take the single step trap before the execution of the original FP instruction completes.

Implication: A Single Step trap will be taken when not expected.

Workaround: None identified.

Status: For the steppings affected, see the *Summary Tables of Changes*.

AL10. BTS (Branch Trace Store) and PEBS (Precise Event Based Sampling) May Update Memory outside the BTS/PEBS Buffer

Problem: If the BTS/PEBS buffer is defined such that:

"The difference between BTS/PEBS buffer base and BTS/PEBS absolute maximum is not an integer multiple of the corresponding record sizes

"BTS/PEBS absolute maximum is less than a record size from the end of the virtual address space

"The record that would cross BTS/PEBS absolute maximum will also continue past the end of the virtual address space

A BTS/PEBS record can be written that will wrap at the 4G boundary (IA32) or 2^{64} boundary (EM64T mode), and write memory outside of the BTS/PEBS buffer.

Implication: Software that uses BTS/PEBS near the 4G boundary (IA32) or 2^{64} boundary (EM64T mode), and defines the buffer such that it does not hold an integer multiple of records can update memory outside the BTS/PEBS buffer.

Workaround: Define BTS/PEBS buffer such that BTS/PEBS absolute maximum minus BTS/PEBS buffer base is integer multiple of the corresponding record sizes as recommended in the IA-32 Intel® Architecture Software Developer's Manual, Volume 3.

Status: For the steppings affected, see the *Summary Tables of Changes*.

AL11. Control Register 2 (CR2) Can be Updated during a REP MOVSB/STOSB Instruction with Fast Strings Enabled

Problem: Under limited circumstances while executing a REP MOVSB/STOSB string instruction, with fast strings enabled, it is possible for the value in CR2 to be changed as a result of an interim paging event, normally invisible to the user. Any higher priority architectural event that arrives and is handled while the interim paging event is occurring may see the modified value of CR2.

Implication: The value in CR2 is correct at the time that an architectural page fault is signaled. Intel has not observed this erratum with any commercially available software.

Workaround: None identified.

Status: For the steppings affected, see the *Summary Tables of Changes*.

AL12. REP STOSB/MOVSB Instructions with RCX $\geq 2^{32}$ May Cause a System Hang

Problem: In IA-32e mode using Intel EM64T-enabled processors, executing a repeating string instruction with the iteration count greater than or equal to 2^{32} and a pending event may cause the REP STOSB/MOVSB instruction to live lock and hang.

Implication: When this erratum occurs, the processor may live lock and result in a system hang. Intel has not observed this erratum with any commercially available software.



Workaround: Do not use strings larger than 4 GB.

Status: For the steppings affected, see the *Summary Tables of Changes*.

AL13. A 64-Bit Value of Linear Instruction Pointer (LIP) May be Reported Incorrectly in the Branch Trace Store (BTS) Memory Record or in the Precise Event Based Sampling (PEBS) Memory Record

Problem: On a processor supporting Intel® EM64T,

"If an instruction fetch wraps around the 4G boundary in Compatibility Mode, the 64-bit value of LIP in the BTS memory record will be incorrect (upper 32 bits will be set to FFFFFFFFh when they should be 0).

"If a PEBS event occurs on an instruction whose last byte is at memory location FFFFFFFFh, the 64-bit value of LIP in the PEBS record will be incorrect (upper 32 bits will be set to FFFFFFFFh when they should be 0).

Implication: Intel has not observed this erratum on any commercially available software.

Workaround: None identified.

Status: For the steppings affected, see the *Summary Tables of Changes*.

AL14. Access to an Unsupported Address Range in Uniprocessor (UP) or Dual-processor (DP) Systems Supporting Intel® Virtualization Technology May Not Trigger Appropriate Actions

Problem: When using processors supporting Intel® Virtualization Technology and configured as dual- or single-processor-capable (i.e. not multiprocessor-capable), the processor should perform address checks using a maximum physical address width of 36. Instead, these processors will perform address checks using a maximum physical address width of 40.

Implication: Due to this erratum, actions which are normally taken upon detection of an unsupported address may not occur. Software which does not attempt to access unsupported addresses will not experience this erratum.

Workaround: None identified.

Status: For the steppings affected, see the *Summary Tables of Changes*.

AL15. Two Correctable L2 Cache Errors in Close Proximity May Cause a System Hang

Problem: If two correctable L2 cache errors are detected in close proximity to each other, a livelock may occur as a result of the processor being unable to resolve this condition.

Implication: When this erratum occurs, the processor may livelock and result in a system hang. Intel has only observed this erratum while injecting cache errors in simulation.

Workaround: None identified.

Status: For the steppings affected, see the *Summary Tables of Changes*.

AL16. Processor May Hang with a 25% or Less STPCLK# Duty Cycle

Problem: If a system de-asserts STPCLK# at a 25% or less duty cycle and the processor thermal control circuit (TCC) on-demand clock modulation is active, the processor may hang. This erratum does not occur under the automatic mode of the TCC.

Implication: When this erratum occurs, the processor may hang.

Workaround: If use of the on-demand mode of the processor's TCC is desired in conjunction with STPCLK# modulation, then assure that STPCLK# is not asserted at a 25% duty cycle.

Status: For the steppings affected, see the *Summary Tables of Changes*.

**AL17. Machine Check Exceptions May not Update Last-Exception Record MSRs (LERs)**

Problem: The Last-Exception Record MSRs (LERs) may not get updated when Machine Check Exceptions occur

Implication: When this erratum occurs, the LER may not contain information relating to the machine check exception. They will contain information relating to the exception prior to the machine check exception.

Workaround: None identified

Status: For the steppings affected, see the *Summary Tables of Changes*.

AL18. Writing the Local Vector Table (LVT) when an Interrupt is Pending May Cause an Unexpected Interrupt

Problem: If a local interrupt is pending when the LVT entry is written, an interrupt may be taken on the new interrupt vector even if the mask bit is set.

Implication: An interrupt may immediately be generated with the new vector when a LVT entry is written, even if the new LVT entry has the mask bit set. If there is no Interrupt Service Routine (ISR) set up for that vector the system will GP fault. If the ISR does not do an End of Interrupt (EOI) the bit for the vector will be left set in the in-service register and mask all interrupts at the same or lower priority.

Workaround: Any vector programmed into an LVT entry must have an ISR associated with it, even if that vector was programmed as masked. This ISR routine must do an EOI to clear any unexpected interrupts that may occur. The ISR associated with the spurious vector does not generate an EOI, therefore the spurious vector should not be used when writing the LVT.

Status: For the steppings affected, see the *Summary Tables of Changes*.

AL19. L2 Cache ECC Machine Check Errors May be erroneously Reported after an Asynchronous RESET# Assertion

Problem: Machine check status MSRs may incorrectly report the following L2 Cache ECC machine-check errors when cache transactions are in-flight and RESET# is asserted:

- Instruction Fetch Errors (IA32_MC2_STATUS with MCA error code 153)
- L2 Data Write Errors (IA32_MC1_STATUS with MCA error code 145)

Implication: Uncorrected or corrected L2 ECC machine check errors may be erroneously reported. Intel has not observed this erratum on any commercially available system.

Workaround: When a real run-time L2 Cache ECC Machine Check occurs, a corresponding valid error will normally be logged in the IA32_MC0_STATUS register. BIOS may clear IA32_MC2_STATUS and/or IA32_MC1_STATUS for these specific errors when IA32_MC0_STATUS does not have its VAL flag set.

Status: For the steppings affected, see the *Summary Tables of Changes*.

AL20. VMCALL to Activate Dual-monitor Treatment of SMIs and SMM Ignores Reserved Bit settings in VM-exit Control Field

Problem: Processors supporting Intel® Virtualization Technology can execute VMCALL from within the Virtual Machine Monitor (VMM) to activate dual-monitor treatment of SMIs and SMM. Due to this erratum, if reserved bits are set to values inconsistent with VMX Capability MSRs, VMCALL may not VMFail.

Implication: VMCALL executed to activate dual-monitor treatment of SMIs and SMM may not VMFail due to incorrect reserved bit settings in VM-Exit control field.

Workaround: It is possible for the BIOS to contain a workaround for this erratum.

Status: For the steppings affected, see the *Summary Tables of Changes*.



AL21. Using 2M/4M Pages When A20M# Is Asserted May Result in Incorrect Address Translations

Problem: An external A20M# pin if enabled forces address bit 20 to be masked (forced to zero) to emulate real-address mode address wraparound at 1 megabyte. However, if all of the following conditions are met, address bit 20 may not be masked:

"paging is enabled

"a linear address has bit 20 set

"the address references a large page

"A20M# is enabled

Implication: When A20M# is enabled and an address references a large page the resulting translated physical address may be incorrect. This erratum has not been observed with any commercially available operating system.

Workaround: Operating systems should not allow A20M# to be enabled if the masking of address bit 20 could be applied to an address that references a large page. A20M# is normally only used with the first megabyte of memory.

Status: For the steppings affected, see the *Summary Tables of Changes*.

AL22. Writing Shared Unaligned Data that Crosses a Cache Line without Proper Semaphores or Barriers May Expose a Memory Ordering Issue

Problem: Software which is written so that multiple agents can modify the same shared unaligned memory location at the same time may experience a memory ordering issue if multiple loads access this shared data shortly thereafter. Exposure to this problem requires the use of a data write which spans a cache line boundary.

Implication: This erratum may cause loads to be observed out of order. Intel has not observed this erratum with any commercially available software or system.

Workaround: Software should ensure at least one of the following is true when modifying shared data by multiple agents:

"The shared data is aligned

"Proper semaphores or barriers are used in order to prevent concurrent data accesses

Status: For the steppings affected, see the *Summary Tables of Changes*.

AL23. The IA32_MC0_STATUS and IA32_MC1_STATUS Overflow Bit is not set when Multiple Un-correctable Machine Check Errors Occur at the Same Time

Problem: When two enabled MC0/MC1 un-correctable machine check errors are detected in the same bank in the same internal clock cycle, the highest priority error will be logged in IA32_MC0_STATUS / IA32_MC1_STATUS register, but the overflow bit may not be set.

Implication: The highest priority error will be logged and signaled if enabled, but the overflow bit in the IA32_MC0_STATUS/ IA32_MC1_STATUS register may not be set.

Workaround: None identified.

Status: For the steppings affected, see the *Summary Tables of Changes*.

AL24. IRET under Certain Conditions May Cause an Unexpected Alignment Check Exception

Problem: In IA-32e mode, it is possible to get an Alignment Check Exception (#AC) on the IRET instruction even though alignment checks were disabled at the start of the IRET. This can only occur if the IRET instruction is returning from CPL3 code to CPL3 code. IRETs from CPL0/1/2 are not affected. This erratum can occur if the EFLAGS value on the



stack has the AC flag set, and the interrupt handler's stack is misaligned. In IA-32e mode, RSP is aligned to a 16-byte boundary before pushing the stack frame.

Implication: In IA-32e mode, under the conditions given above, an IRET can get a #AC even if alignment checks are disabled at the start of the IRET. This erratum can only be observed with a software generated stack frame.

Workaround: Software should not generate misaligned stack frames for use with IRET.

Status: For the steppings affected, see the *Summary Tables of Changes*.

AL25. Processor May Fault When the Upper 8 Bytes of Segment Selector Is Loaded from a Far Jump through a Call Gate via the Local Descriptor Table

Problem: In IA-32e mode of the Intel EM64T processor, control transfers through a call gate via the Local Descriptor Table (LDT) that uses a 16-byte descriptor, the upper 8-byte access may wrap and access an incorrect descriptor in the LDT. This only occurs on an LDT with a LIMIT > 0x10008 with a 16-byte descriptor that has a selector of 0xFFFC.

Implication: In the event this erratum occurs, the upper 8-byte access may wrap and access an incorrect descriptor within the LDT, potentially resulting in a fault or system hang. Intel has not observed this erratum with any commercially available software.

Workaround: None identified.

Status: For the steppings affected, see the *Summary Tables of Changes*.

AL26. The Processor May Issue Front Side Bus Transactions up to 6 Clocks after RESET# is Asserted

Problem: The processor may issue transactions beyond the documented 3 Front Side Bus (FSB) clocks and up to 6 FSB clocks after RESET# is asserted in the case of a warm reset. A warm reset is where the chipset asserts RESET# when the system is running.

Implication: The processor may issue transactions up to 6 FSB clocks after the RESET# is asserted

Workaround: None identified.

Status: For the steppings affected, see the *Summary Tables of Changes*.

AL27. Front Side Bus Machine Checks May be Reported as a Result of On-Going Transactions during Warm Reset

Problem: Processor Front Side Bus (FSB) protocol/signal integrity machine checks may be reported if the transactions are initiated or in-progress during a warm reset. A warm reset is where the chipset asserts RESET# when the system is running.

Implication: The processor may log FSB protocol/signal integrity machine checks if transactions are allowed to occur during RESET# assertions.

Workaround: BIOS may clear FSB protocol/signal integrity machine checks for systems/chipsets which do not block new transactions during RESET# assertions.

Status: For the steppings affected, see the *Summary Tables of Changes*

AL28. NMI-blocking Information Recorded in VMCS May be Incorrect after a #GP on an IRET Instruction

Problem: In a system supporting Intel® Virtualization Technology, the NMI blocking bit in the Interruption-Information Field in the guest VMCS may be set incorrectly. This erratum will happen if a VMExit occurs for a #GP fault on an IRET instruction due to an EIP that violates the segment limit or is non-canonical.

Implication: If this erratum occurs, monitor software may not be able to handle #GP and then inject an NMI since monitor software does not have information about whether NMIs are blocked in the guest.

Workaround: Monitor software can workaround this bug by avoiding injection of NMI after #GP emulation.



Status: For the steppings affected, see the *Summary Tables of Changes*.

AL29. VMLAUNCH/VMRESUME May Not Fail when VMCS is Programmed to Cause VM Exit to Return to a Different Mode

Problem: VMLAUNCH/VMRESUME instructions may not fail if the value of the "host address-space size" VM-exit control differs from the setting of IA32_EFER.LMA.

Implication: Programming the VMCS to allow the monitor to be in different modes prior to VMLAUNCH/VMRESUME and after VM-exit may result in undefined behavior.

Workaround: Software should ensure that "host address-space size" VM-exit control has the same value as IA32_EFER.LMA at the time of VMLAUNCH/VMRESUME.

Status: For the steppings affected, see the *Summary Tables of Changes*.

AL30. A Machine Check Exception (MCE) Occurring during an Enhanced Intel SpeedStep® Technology Ratio Change May Cause Both Processor Cores to Lock Up

Problem: If an MCE and an Enhanced Intel SpeedStep® Technology frequency ratio change occur within a small timing window both processor cores may stop executing instructions. The MCERR# signal is correctly asserted for the Machine Check Exception.

Implication: The system will stop operating. A hardware reset is required to recover from this condition. Intel has not observed this erratum with any commercially available software, or system.

Workaround: None identified.

Status: For the steppings affected, see the *Summary Tables of Changes*.

AL31. BIST Error Reported on Secondary Logical Processor of Each Core

Problem: The processor cores execute BIST (Built-in Self Test) after RESET if commanded by the Power-On Configuration setting. The secondary logical processor in each core will always declare a BIST failure.

Implication: A false BIST failure may be detected on the secondary logical processor.

Workaround: BIOS should use the primary logical processor BIST results for both the primary and secondary logical processors in each core. BIOS should ignore the BIST result in EAX [Bit13] for the secondary logical processor in each core.

Status: For the steppings affected, see the *Summary Tables of Changes*.

AL32. When Enhanced Halt State is Enabled and Thermal Monitor 2 is Disabled a System Hang may Occur

Problem: With Enhanced Halt State (C1E) enabled and Thermal Monitor 2 (TM2) disabled a system hang may occur after the following sequence of events:

1. C1E is enabled. IA32_MISC_ENABLE MSR (1A0H), Bit [25] = 1.
2. TM2 is disabled. IA32_MISC_ENABLE MSR (1A0H), Bit [13] = 0.
3. All four threads of the processor enter the C1E state.
4. FORCEPR# is asserted. (This may happen if a different processor asserts PROCHOT# and the system asserts FORCEPR# to all sockets in response.)
5. While FORCEPR# is still active, an Interrupt is accepted that causes the processor to exit the C1E state.

Intel® Xeon® Processor 7100 Series, processor numbers 7140 and 7130 are affected by this erratum. Processor numbers 7120 and 7110 are not affected by this erratum. Software may use the IA32_PLATFORM_ID MSR (17H), Bits[52:50] to determine if the processor is affected. A Platform ID of '001' (Processor Flag 1) is affected and Platform ID of '101' (Processor Flag 5) is not affected by this erratum.



Implication: A system hang may occur. Intel has not observed this erratum with any commercially available software.

Workaround: Enable TM2, IA32_MISC_ENABLE MSR (1A0H), Bit [13] = 1.

Status: For the steppings affected, see the *Summary Tables of Changes*.

AL33. Lock Interaction between Two Logical Processors within a Core may Cause a Stall in Code Execution

Problem: Problem: A logical processor may temporarily stall code execution in an HT Technology enabled system when the following sequence occurs:

- A logical processor executes a tight synchronization loop that includes a stream of locks, which propagate to the FSB. This will not occur if the lock access is satisfied from the internal cache.
- The second logical processor within the same| core executes other instructions. Logical processors that are not within the same core are not affected by this issue.

Locks that are not split across a cache line and execute from write-back cacheable memory will not cause this issue. The interaction must occur in a particular timing window which may cause the logical processor in the synchronization sequence to stall until the arrival of an interrupt or other FSB transaction.

Implication: If this erratum occurs in an HT Technology enabled system, the affected application may temporarily stop making forward progress. Intel has not observed this erratum with any commercially available software.

Workaround: None identified.

Status: For the steppings affected, see the *Summary Tables of Changes*.

AL34. Periodic Thermal Throttling/STPCLK Events in the Presence of High Memory Latency Accesses Could Lead to a System Hang

Problem: The system may hang when the following conditions are met:

1. Periodic STPCLK mechanism is enabled via the chipset or the processor enters thermal throttling from activation of the thermal control circuit (TCC).
2. Hyper-Threading Technology is enabled
3. One logical processor is trying to service an event (i.e. hardware interrupt)
4. The other logical processor executes code and the latency for any memory accesses are long enough for STPCLK to be re-asserted or the processor re-enters throttling

Implication: If this erratum occurs, the processor will go into and out of the sleep state or thermal throttling without making forward progress, since the logical processor will not be able to service any pending event. Intel has not observed this erratum with any commercially available software or system.

Workaround: None identified.

Status: For the steppings affected, see the *Summary Tables of Changes*.

AL35. Reduced End-Agent Low side FSB Margin may occur with High Impedance Boards Operating at Low Temperatures

Problem: With a fully populated (end-agent processor, mid-agent processor and chipset) FSB operating at 800 MTS (Mega Transfers per Second), certain Intel® 8501 Chipset North Bridge components may cause the end-agent processor to post FSB single-bit correctable (SBC) events. This occurs more frequently on a high impedance board operating at low temperatures.

Implication: There is no functional impact to the system, it will continue to run with no performance impact. The system may see an increase in FSB SBC events, which result in a posting



to the MC4_STATUS MSR (0x411). A Machine Check exception is not generated on an SBC event.

Workaround: It is possible for the BIOS to contain a workaround for this erratum.

Status: For the steppings affected, see the *Summary Tables of Changes*.

AL36. L3 Cache Errors Occurring During an INVD or WBINVD Instruction May not Generate a Machine Check Exception

Problem: L3 Cache Errors which occur during a INVD or WBINVD instruction may not generate a Machine Check Exception.

Implication: The L3 Cache error is not reported. Intel has not observed this erratum with any commercially available software, or system.

Workaround: None identified.

Status: For the steppings affected, see the *Summary Tables of Changes*.

AL37. A Continuous Loop Executing Bus Lock Transactions on One Logical Processor may Prevent Another Logical Processor from Acquiring Resource

Problem: In a system supporting Hyper-Threading Technology, when one hardware thread is in a continuous loop executing bus locks plus other traffic, the other hardware thread may be prevented from acquiring resources to also execute a lock.

Implication: This erratum may cause system hang or unpredictable system behavior. This erratum has not been observed with commercially available software.

Workaround: None identified.



Specification Changes

There are no new Specification Changes for this revision.

The Specification Changes listed in this section apply to the following documents:

1. *Dual-Core Intel® Xeon® Processor 7100 Series Datasheet*

All Specification Changes will be incorporated into a future version of the appropriate Dual-Core Intel Xeon Processor 7100 Series documentation.



Specification Clarifications

There are no new Specification Clarifications for this revision.

The Specification Clarifications listed in this section apply to the following documents:

1. *Dual-Core Intel® Xeon® Processor 7100 Series Datasheet*

All Specification Clarifications will be incorporated into a future version of the appropriate Dual-Core Intel® Xeon® Processor 7100 Series documentation.

⚠ Intel processor numbers are not a measure of performance. Processor numbers differentiate features within each processor family, not across different processor families. Over time processor numbers will increment based on changes in clock, speed, cache, FSB, or other features, and increments are not intended to represent proportional or quantitative increases in any particular feature. Current roadmap processor number progression is not necessarily representative of future roadmaps. See www.intel.com/products/processor_number for details.



Documentation Changes

There are no new Documentation Changes for this revision.

The Documentation Changes listed in this section apply to the following documents:

1. *Dual-Core Intel® Xeon® Processor 7100 Series Datasheet*

All Documentation Changes will be incorporated into a future version of the appropriate Dual-Core Intel® Xeon® Processor 7100 Series documentation.

Note:

Documentation changes for *IA-32 Intel® Architecture Software Developer's Manual* volumes 1, 2A, 2B, and 3 will be posted in the separate document *IA-32 Intel® Architecture Software Developer's Manual Documentation Changes*. Follow the link below to become familiar with this file.

<http://developer.intel.com/design/pentium4/specupdt/252046.htm>

